Technical Bulletin



SERVICE BULLETIN

OLIVIOL BOLLLIII		
Classification:	Reference:	Date:
EL06-021a	NTB07-005a	January 6, 2009

BCM INSPECTION AND CONFIGURATION DURING REPLACEMENT

This bulletin has been amended to announce the availability of this procedure within the CONSULT-III Operation Manual. Please discard all previous copies of this bulletin.

APPLIED VEHICLES: All models equipped with a configurable BCM

SERVICE INFORMATION

- The "BCM Inspection and Configuration During Replacement" Service Procedure will no longer be available in Technical Service Bulletins.
- The step-by-step procedure is now available only in the CONSULT-III Operation Manual.
- For security reasons, the Manual is blocked from print functions.

To Locate this Service Procedure within the CONSULT-III Operation Manual:

- 1. From the Main Menu page in ASIST, select **INFO. Tool Box**.
- 2. Select Specialty Tools.
- 3. Select **CONSULT-III Operation Manual**.
- 4. From the Manual Selection window, select **CONSULT-III Operation Manual**.
- 5. Select your language preference.
- 6. Select **Repair** from the navigation bar on the left side of the screen.
- 7. Select **Configuration** under Electronic Repair System Selection.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.